

**\*\*ATTENTION\*\***

**Important Information about French .50 caliber ammunition.**

There is an issue with primer detonation on one type of French manufactured .50 caliber ammunition we recently imported. This ammunition was made using two types of primer. One is brass or yellow colored and the other is silver. The brass colored primer does not work reliably. The silver colored primer works fine and is 100% first class ammunition. We are replacing all of the brass colored primer ammunition. The replacement ammunition has been tested by H.P. White laboratory, and is top-notch stuff. If you have any French .50 caliber with brass colored primers, please call us at 1 800 270-2767 to arrange for replacement. If you have French .50 caliber ammunition with silver colored primers your ammunition is 100% OK.



**Gold primed Picture**  
Call 1 800 270-2767 for replacement.



**Silver primed Picture**  
Enjoy your day at the range!